

Inspection report – 2016 Doosan 966H

Serial No: ABCD123457890123456 | Hours: 5436 | Location: Dubai, United Arab Emirates | SKU: 10397

Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	Yes
Ripper Control Valve	Yes
Low Ground Pressure Tracks	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A
Radio	Yes
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok, has a cut
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	C15
Engine Cooling System	Ok
Engine Oil Check	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Push Frame & Trunnions	Ok
Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Ok
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Ok, lights need wiring connecting
Push Arm Pivot Shaft	Ok
Tilt Linkage Pins & Bushings	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift Hydraulic Jacks	Ok
Ripper Lift Hydraulic Jacks	Ok
Tilt Hydraulic Jack	Ok
Angle Hydraulic Jack	N/A
Ripper Angle Hydraulic Jacks	Ok

Limited Functional Testing & Operation

Push Frame Pins	Ok, minor Loose
Blade Pins	Ok, minor Loose
Ripper Pins	Ok
Equalizer Bar Condition	Ok
Bulldozer Stall Test	Ok
Steering Function Test	Ok
Blade Tilt and Lift Test	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Undercarriage Pivot Pins	Ok, minor Loose
Transmission Test	Ok
Brake System Test	Ok
Torque Converter Test	Ok
Electric system check	Ok

Blade Inspection

Blade Base Condition	Ok
Spill Rack Condition	Ok
Blade Front Condition	Ok
Blade Edge Condition	Ok

Undercarriage Inspection

Right Side Undercarriage Condition	-
Undercarriage Bushings	75%
Undercarriage Shoes	80%
Front Idler Condition	80%
Rear Idler Condition	70%
Carrier Roller Condition	N/A
Track Links Condition	80%
Sprocket Condition	70%
Roller Condition	60%
Track Canon Condition	70%
Left Side Undercarriage Condition	-
Undercarriage Bushings	75%
Undercarriage Shoes	80%
Front Idler Condition	80%
Rear Idler Condition	80%
Carrier Roller Condition	N/A
Track Links Condition	80%
Sprocket Condition	70%
Roller Condition	60% , one need change
Track Canon Condition	70%
Track Width Measurement	W560 / L240 /Grouser height 45 mm



No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

