

# Inspection report – 2022 Caterpillar 966H

Location: Jeddah, United Arab Emirates | SKU: 371551

#### **Key Features & Condition**

Safety Certification Label N ABoom Hydraulic Check Valve Yes Adjustable Boom System N/A **Automatic Lubrication System** Yes Arm Hydraulic Check Valve Yes Diesel Particulate Filter N\A Hydraulic Hammer Lines N/A N\A Grapple and Shear Hydraulic Lines Diesel Exhaust Fluid System AddBlue N AStabilizer Blade Condition N\A Yes Horn

#### **Operator Cabin Details**

Seat and Arm Support Ok
Cab Doors & covers Ok
Control Levers, Control Stick Ok

Windows and Mirrors Ok, Left mirror are missing

Dashboard Screen, Gauges Ok

Warning alarms message Water meter sensor

Washer, Wipers Ok

Air Conditioning & Heating System Ok, Not cooling

Cab Floor Covering Ok
Cab Structure, Gard Ok
Electrical System Ok

#### **Engine & Performance**

Fuel Injection System Electronic

Engine Model SAA6D125E-5

Engine Cooling System OK

#### **PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



# PLANT & EQUIPMENT AUCTIONS

Engine Oil Check OK
Cooling System OK

Coolant OK, Normal water

Exhaust System & Muffler OK
Belts & Air/Oil Filters OK

Smoke Check Normal Blow BY Normal

Leaks & Seals Ok

## **Exterior Condition & Visual Inspection**

Main Frame & Track Frame Ok **Protective Covers & Sheets** Ok **Engine Hood** Ok Side Access Doors Ok Steps and Handrails Ok **Boom Condition** Ok **Bumpers & Catwalk Condition** Ok **Arm Condition** Ok

Lights Ok, One light need bulb

Battery Check Ok
Cabin Compartments Ok

Exterior Paint Condition Ok, Some parts repainted

#### **Hydraulic System**

Hydraulic Leaks Ok
Boom Hydraulic Jack Ok
Hydraulic Pump & Valve Block Ok
Bucket Hydraulic Jack Ok
Arm Hydraulic Jack Ok

## Performance analysis

Boom Pins Condition Ok
Excavator self- Drift Test Ok

Arm Pins Condition Ok, Minor loose

#### **PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



# PLANT & EQUIPMENT AUCTIONS

Hydraulic Pump Noise Check Ok

Bucket Pins Condition Ok, Minor loose Slewing Ring Bearing Movement Check Ok, Minor loose

Swing Drive and Brake Test Ok
Drive force Test Ok

#### **Attachments**

Attachments model bucket

Size W1750 \H1750 \D115

Status OK

Coupler Status Minor welded

Second Attachments model N\A
Size N\A
Status N\A

## **Undercarriage**

**Bushings** 60% Track Shoes 80% 60% Idlers Shoe Width in mm: 800mm Track Pitch in mm: 60mm **Carrier Rollers** 60% Track Rollers 60% Track Links 70% **Sprocket Segments** 70%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

