

Inspection report – 2022 Caterpillar 966H

Location: Jeddah, United Arab Emirates | SKU: 427551

Key Features & Condition

| | |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Ground Ripper | Yes |
| Ripper Control Valve | Yes |
| Low Ground Pressure Tracks | N/A |
| Operator's Manual | N/A |
| Emission Compliance Label | N/A |
| Grade Control System | N/A |
| Equipment Parts Manual | N/A |
| CAT System One | N/A |
| Radio | Yes |
| Horn | Yes |

Operator Cabin Details

| | |
|-----------------------------------|---------------|
| Seat and Arm Support | Ok |
| Cab Doors & covers | Ok |
| Controls, Levers | Ok |
| Windows and Mirrors | Ok |
| Dashboard Screen, Gauges | Ok |
| Warning alarms message | Ok |
| Washer, Wipers | Ok |
| Air Conditioning & Heating System | Not cooling |
| Cab Floor Covering | Ok, has a cut |
| Cab Structure, Gard | Ok |
| Electrical System | Ok |

Engine & Performance

| | |
|-----------------------|------------|
| Fuel Injection Type | Electronic |
| Engine Model | C15 |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Blowby | Normal |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|------------------|
| Exhaust System & Muffler | Ok |
| Belts & Air/Oil Filters | Ok |
| Smoke | Normal |
| Coolant | Ok, normal water |
| Fluid Leaks | Ok |

Exterior Condition & Visual Inspection

| | |
|-----------------------------------|-----------------------------------|
| Push Frame & Trunnions | Ok |
| Doors, Covers, and Grilles | Ok |
| Access Steps & Handrails | Ok |
| Exterior Paint Condition | Ok |
| Blade Trunnions & Bushings | Ok |
| Underbody Protection Plates | Ok |
| Final Drive Condition | Ok |
| Fuel Tank, Roof, & Hood Condition | Ok |
| Lights and Battery Check | Ok, lights need wiring connecting |
| Push Arm Pivot Shaft | Ok |
| Tilt Linkage Pins & Bushings | Ok |

Hydraulic System

| | |
|------------------------------|-----|
| Hydraulic Leaks | Ok |
| Lift Hydraulic Jacks | Ok |
| Ripper Lift Hydraulic Jacks | Ok |
| Tilt Hydraulic Jack | Ok |
| Angle Hydraulic Jack | N/A |
| Ripper Angle Hydraulic Jacks | Ok |

Limited Functional Testing & Operation

| | |
|--------------------------|-----------------|
| Push Frame Pins | Ok, minor Loose |
| Blade Pins | Ok, minor Loose |
| Ripper Pins | Ok |
| Equalizer Bar Condition | Ok |
| Bulldozer Stall Test | Ok |
| Steering Function Test | Ok |
| Blade Tilt and Lift Test | Ok |
| Undercarriage Pivot Pins | Ok, minor Loose |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|-----------------------|----|
| Transmission Test | Ok |
| Brake System Test | Ok |
| Torque Converter Test | Ok |
| Electric system check | Ok |

Blade Inspection

| | |
|-----------------------|----|
| Blade Base Condition | Ok |
| Spill Rack Condition | Ok |
| Blade Front Condition | Ok |
| Blade Edge Condition | Ok |

Undercarriage Inspection

| | |
|------------------------------------|-----------------------------------|
| Right Side Undercarriage Condition | - |
| Undercarriage Bushings | 75% |
| Undercarriage Shoes | 80% |
| Front Idler Condition | 80% |
| Rear Idler Condition | 70% |
| Carrier Roller Condition | N/A |
| Track Links Condition | 80% |
| Sprocket Condition | 70% |
| Roller Condition | 60% |
| Track Canon Condition | 70% |
| Left Side Undercarriage Condition | - |
| Undercarriage Bushings | 75% |
| Undercarriage Shoes | 80% |
| Front Idler Condition | 80% |
| Rear Idler Condition | 80% |
| Carrier Roller Condition | N/A |
| Track Links Condition | 80% |
| Sprocket Condition | 70% |
| Roller Condition | 60% , one need change |
| Track Canon Condition | 70% |
| Track Width Measurement | W560 / L240 /Grouser height 45 mm |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

