

## Rapport d'inspection – 1993 Komatsu WA600-1

Numéro de série: A10311 | Heure: 78949 | Lieu: United Arab Emirates | SKU: 2426

---

### Specifications and Standards

|                   |     |
|-------------------|-----|
| 4WD               | N/A |
| Draw Bar          | N/A |
| Spare Tire        | N/A |
| Xenon Head Lights | N/A |
| Gear Shift Paddle | Ok  |
| Rear Camera       | N/A |
| Air Condition     | Ok  |
| Radio             | Ok  |
| 7 Seats           | N/A |

---

### Interior

|                 |                 |
|-----------------|-----------------|
| Seats           | Ok              |
| Switches        | Ok              |
| Gauges          | Ok              |
| Aircon / Heater | Ok              |
| Ceiling         | Ok              |
| Cab Doors       | Ok              |
| Windows         | Ok              |
| Wipers          | Ok, Motor sound |
| Floor Mats      | Ok              |

---

### Engine

|                |                    |
|----------------|--------------------|
| Model          | I-VTEC             |
| Leaks          | Ok                 |
| Oil Condition  | Ok                 |
| Exhaust        | Ok                 |
| Cooling System | Ok\Coolant \Normal |
| Fuel Type      | Gasoline           |
| Sound          | Ok                 |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|         |             |
|---------|-------------|
| Blow By | Ok\Normal   |
| Belts   | Ok          |
| Power   | Ok          |
| Size    | 1500cc\1.5L |

---

## Exterior

|                    |                               |
|--------------------|-------------------------------|
| Chassis            | Lower left crossbar scratched |
| Under Engine Cover | Missing                       |
| Door Handles       | Ok                            |
| Paintwork          | Ok, Two pieces repainted      |
| Cooler Grill       | Ok                            |
| Bumpers            | Ok                            |
| Lights             | Ok                            |

---

## Power Train

|                   |    |
|-------------------|----|
| Axels             | Ok |
| Gearbox           | Ok |
| Transmission Gear | Ok |
| Transfer Gear     | Ok |
| Universal Joints  | Ok |
| Differentials     | Ok |
| Brake Drums/Disk  | Ok |

---

## Limited Functional Test

|               |    |
|---------------|----|
| Drive Forward | Ok |
| Drive Reverse | Ok |
| Service Brake | Ok |
| Steering      | Ok |
| Wheel Bearing | Ok |
| Suspensions   | Ok |
| Park Brake    | Ok |

---

## Tires Axle 1

|                 |                   |
|-----------------|-------------------|
| RHS mm (%) rem. | 40% - 2023 \NEXEN |
|-----------------|-------------------|

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|            |                   |
|------------|-------------------|
| LHS mm (%) | 40% - 2023 \NEXEN |
| Cuts       | Ok                |
| Recapped   | Ok                |

Tires Axle 1

|                 |                       |
|-----------------|-----------------------|
| RHS mm (%) rem. | 50% - 2022 \ROADMARCH |
| LHS mm (%)      | 40% - 2021\BRIDGESONE |
| Cuts            | Ok                    |
| Recapped        | Ok                    |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

